

Figure 1. June 2011 DMR.




Figure 2. Operations log for Tensed.




Figure 3. Calculation sheet for June 2011 DMR.



Figure 4. Operator unlocking lift station at lagoon site.

City of Tensed ID-0025101 Inspection Date: 7/26/2011 Photo Log TRIM Record: 2011AGF2210 Page **2** of **11**



Figure 5. Interior of lift station at lagoon site.



ID-0025101

TRIM Record: 2011AGF2210

Figure 6. Pump control panel at lagoon site.

City of Tensed Photo Log Inspection Date: 7/26/2011 Page **3** of **11**



Figure 7. Lagoon site copy of Operation and Maintenance manual kept below pump controls.



Figure 8. Looking west at Lagoon #2.

City of Tensed Photo Log ID-0025101 Inspection Date: 7/26/2011 TRIM Record: 2011AGF2210 Page **4** of **11**



Figure 9. Looking west at a moose in corner of Lagoon #2. Note weed growth along lagoon berms.



Inspection Date: 7/26/2011

Page **5** of **11**

Figure 10. Looking northeast at inlet (smooth water area) into Lagoon #1.

City of Tensed ID-0025101
Photo Log TRIM Record: 2011AGF2210



Figure 11. Transfer structure from lagoons to disinfection.



Figure 12. Sodium hypochlorite tablet holder in disinfection chamber.

City of Tensed ID-0025101 Inspection Date: 7/26/2011 Photo Log TRIM Record: 2011AGF2210 Page **6** of **11**



ID-0025101

TRIM Record: 2011AGF2210

Figure 13. Valve to allow effluent to flow through disinfection chamber.



Figure 14. Surface above chlorine contact chamber (under dead grass).



Figure 15. Flow structure between chlorine contact chamber and final settling pond (hidden in long grass and weeds).

City of Tensed ID-0025101 Inspection Date: 7/26/2011 Photo Log TRIM Record: 2011AGF2210 Page **8** of **11**



Figure 16. Final settling pond prior to discharge.



ID-0025101

TRIM Record: 2011AGF2210

Figure 17. Effluent sampling weir.

City of Tensed Photo Log Inspection Date: 7/26/2011 Page **9** of **11**



Figure 18. Interior of effluent sampling weir. Note high water marks in left side of vault, reportedly from high runoff this spring.



Figure 19. Discharge point to Hangman Creek (approximately 200 feet away near center of photo).

City of Tensed ID-0025101 Inspection Date: 7/26/2011 Photo Log TRIM Record: 2011AGF2210 Page 10 of 11



Figure 20. Looking southeast toward Hangman Creek (dark green line of vegetation) from lagoon berm.

ID-0025101 Inspection Date: 7/26/2011 TRIM Record: 2011AGF2210 Page **11** of **11**